



SCHOOL: _____ IMMEDIATE NEEDS:

DON BENITO ES

PRIORITY 2

- A. REDISTRIBUTION OF PARKING LOT(S) WITH EMPHASIS ON INCREASED CAPACITY AND INTRODUCTION OF LOOPED DROP-OFF/PICK-UP AREA.
- B. JOIN UPPER PLAYGROUND TO LOWER FIELD BY CREATION OF AN ELEVATOR SYSTEM.
- C. REPLACE K PORTABLES WITH NEW PERMANENT BUILDING. INCREASE KINDERGARTEN PLAYGROUND'S SIZE.
- D. MAKE ROOM ABOVE ADMINISTRATION USABLE TO SCHOOL AND COMMUNITY BY CONSTRUCTION OF BRIDGE FROM DENAIR ST.
- E. SCHOOL IS IN NEED OF LARGER LIBRARY.
- F. PROVIDE RESTROOM FACILITIES AND DRINKING FOUNTAINS IN LOWER FIELD AND REPLACE OLD PLAYGROUND EQUIPMENT.
- G. UPGRADE LIGHTING IN CORRIDORS IN CLASSROOM BUILDINGS.
- H. PROVIDE INTRUSION ALARM AND SECURITY FENCING.
- I. PROVIDE FURRED WALL IN OFFICE ROOM AT MULTI-PURPOSE ROOM, TO COVER EXPOSED PLUMBING.
- J. PROVIDE ADDITIONAL CUSTODIAL STORAGE SPACE.