

LONGFELLOW ES

PRIORITY 2

- A. REPAIR PERGOLA BY BASEBALL FIELD OR REPLACE WITH NEW.
- B. PROVIDE NOISE MITIGATION MEASURES IN CORRIDORS.
- C. EXPAND PARKING LOT OFF RIO GRANDE ST. AND CREATE DROP-OFF/PICK-UP LOOP IN CAMPUS.
- D. AT THE MAIN SCHOOL BUILDING, ADD WALL AND FLOOR DATA AND POWER OUTLETS, REPLACE THE BASEMENT PLUMBING FIXTURES AND GALVANIZED STEEL PIPING WITH COPPER PIPES AND FITTINGS.
- E. PROVIDE EXHAUST FANS AT RESTROOM.
- F. REPLACE THE SINK AND COUNTER IN THE TEACHER'S LOUNGE.
- G. PROVIDE NEW EXTERIOR LIGHTING WITH PHOTO CELLS AT THE PARKING LOT.
- H. REPLACE THE RUSTY FENCING ON SITE WITH NEW FENCES AND GATES. REPAIR SITE RETAINING WALLS AND REPAINT PEELING CONCRETE WALLS.