

SCHOOL: IMMEDIATE NEEDS:

LOMA ALTA ES

PRIORITY 2

- A. EXPAND OR PROVIDE LARGER TEACHER'S LOUNGE.
- B. RECONFIGURE PARKING LOTS TO MAXIMIZE PARKING SPACE INCLUDING WIDENING OF DRIVEWAY AT LOMA ALTA DR.
- C. BACK-STAGE CHANGING ROOMS NEED TO BE ADAPTED TO NEW USES. UPGRADE LIGHTING AND ALL FINISHES.
- D. REMOVE ABANDONED FIRE SPRINKLER SYSTEM IN BLDG. 'A'.
- E. REPLACE EXTERIOR LIGHTING SYSTEM.
- F. INSTALL IRRIGATION AT K-BUILDING'S WEST SIDE TURF AREA.