



SCHOOL: **PASADENA HS** IMMEDIATE NEEDS:

- A. MODERNIZE GYM TO INCLUDE CENTRAL HVAC, NEW LOCKER ROOM FEATURES; NEW BLEACHERS; REMOVE ASBESTOS FROM GYM COACH OFFICES' FLOORS AND PROVIDE INTERNET CONNECTIONS TO SAME OFFICES.
- B. UPGRADE RESTROOMS THROUGHOUT CAMPUS.
- C. PROVIDE A SECURITY ALARM SYSTEM.
- D. PROVIDE NEW SHADE STRUCTURES AT MAIN QUAD AND WHERE NEEDED.
- E. PROVIDE OUTDOOR SECURITY LIGHTING, PERHAPS WITH MOTION DETECTORS.
- F. PROVIDE A MULTI-PURPOSE ARTIFICIAL FIELD AND TRACK.
- G. PROVIDE PROPER DRAINAGE AT BASEBALL AND SOCCER FIELDS AND REPAIR AND/OR REPLACE SECURITY FENCING. PROVIDE NEW SOFTBALL FIELD.
- H. ADA ISSUES: PROVIDE LANDING AT CLASSROOMS WITH RAISED FLOORS. PROVIDE ACCESS PATH TO ATHLETIC FIELDS. PROVIDE ACCESSIBLE RESTROOMS AT THE GYM/LOCKER ROOM. PROVIDE EXTERIOR DRINKING FOUNTAINS AND ACCESSIBLE FEATURES AT POOL AND POOL DECK.
- I. UPGRADE SANITARY SEWERS AT BUILDINGS 'A', 'E', 'J', 'S', 'T' AND 'W'.
- J. REPLACE OLD ELECTRIC PANELBOARDS AT BUILDINGS 'A', 'B', 'T' AND 'W' WITH ADEQUATE BRANCH BREAKERS WITH INCREASED CAPACITY.
- K. SEPARATE DOMESTIC/FIRE/IRRIGATION METERS.



L. CREATE TEACHERS' LOUNGE.

M. REPLACE INTERIOR LIGHTING WITH HIGH-EFFICIENCY LIGHTING IN BUILDING 'B', 'R', 'S' AND 'T'. REPLACE LIGHTING SYSTEM IN THE LITTLE THEATER.

**ESTIMATED COST OF IMMEDIATE NEEDS:**

**\$ 35,561,404**