



SCHOOL: **WILSON MS** IMMEDIATE NEEDS:

- A. MODERNIZE MAIN BUILDING, CAFETERIA, KITCHEN, AND AUDITORIUM TO CURRENT ELECTRICAL, MECHANICAL, LIGHTING, TECHNOLOGICAL, AND INTERIOR FINISH STANDARDS. REPLACE OUTDATED POWER OUTLETS CATV AND AV EQUIPMENT IN THE AUDITORIUM.
- B. MODERNIZE EXISTING RESTROOMS.
- C. REPAIR ELEVATOR AT GYMNASIUM AND BRING CAMPUS TO CURRENT ADA STANDARDS,
- D. MODERNIZE GYM LOCKER ROOMS
- E. REPLACE RESTROOM PLUMBING FIXTURES AND INTERIOR AND EXTERIOR DRINKING FOUNTAINS WITH ADA COMPLIANT FEATURES.
- F. REPLACE OLD ELECTRIC PANELBOARDS WITH ADEQUATE BRANCH BREAKERS WITH INCREASED CAPACITY AND LIGHTING IN AUDITORIUM AND THE MAIN CLASSROOM BUILDING. UPGRADE HVAC SYSTEM IN AUDITORIUM.
- G. SEPARATE DOMESTIC, FIRE AND IRRIGATION WATER METERS.
- H. PROVIDE ACCESS TO AUDITORIUM STAGE.
- I. MODERNIZE BAND ROOM TO INCLUDE PROVISION OF ACOUSTICAL WALL TREATMENT, BETTER, SECURED STORAGE FOR INSTRUMENTS, NEW SWITCH BOARD, UPGRADED TECHNOLOGY, AND NEW INTERIOR FINISHES.
- J. REPLACE OLD BOILER SYSTEM IN THE MAIN CLASSROOM AND GYM.



K. REPLACE ALL GALVANIZED STEEL WATER PIPING
WITH COPPER.

ESTIMATED COST OF IMMEDIATE NEEDS:

\$ 7,387,794