gkkworks

SCHOOL: IMMEDIATE NEEDS:

WILSON MS

PRIORITY 2

- A. IMPROVE EXTERNAL APPEARANCE OF BUILDINGS INCLUDING REPAIR OR REPLACEMENT OF WOOD WINDOWS. BUILDING 'A' NEEDS ENTIRE EXTERIOR PAINTED.
- B. REPLACE DELAPIDATED FIELD BLEACHERS; PROVIDE OUTDOOR LIGHTING AND NEW FENCING THROUGHOUT TO SECURE CAMPUS.
- C. CONSTRUCT PRIVACY SCREENS AT EXTERIOR ENTRY TO RESTROOMS NEXT TO MAIN QUAD.
- D. REPLACE RUSTED CHAIN LINK FENCING THROUGHOUT CAMPUS.